1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXXX XXXXX – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014










Photos 1 through 4 are the home at XXX Meadowrue Trail and close-ups of the exterior in the area of the interior pipe break.

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXX XXXXXX – for Narragansett Property Management Taken: 1/29 thru 2/3/2014










These digital and thermal images were obtained in the bottom floor bedroom of the raised ranch home immediately below the pipe break.

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXXX XXXXXXX – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014



These images are also the common wall and common corner below the top floor pipe break.

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXXXXXX – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014

\$FLIR \$FLIR °F °F 39 40 1/29/14 3:46:42 p e=0.88 1/29/14 3:46:18 p e=0.88 16)

More basement bedroom images – the staining in image 13 is from the main carrier beam where leaking water turned dark brown and flowed down to the carpet.

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXXXXXXXX – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014



Top floor images- #17 is right at the frozen pipe repair zone. The remaining photos and images show flooring damage.

20)

19)

1/29/14 3:28:13 p e=0.88

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: XXXXX XXXXX – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014









More first floor damage/moisture mapping and drying technique photos

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: xxxxx xxxxxxx – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014






Rescue mat system using the DriEaz InterAir system blowing air in through the toe-kick to salvage cabinets






Basement wall and carpet dryout – We will not be able to save the carpet due to heavy saturation and stains previously mentioned.

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM Property Owner: xxxxxxx xxxxxx – for Narragansett Property Mgt Taken: 1/29 thru 2/3/2014





More basement drying in ongoing photos.





One truck load of debris – debris removed with bags and trash barrels to offsite dumpster.



CONCLUSION & COMMENTS

First floor pipe break that affected first floor flooring with a lot of additional damage to the basement bedroom below it. Water is actually flowing through the outside walls of the house.

Todd Pascoe, CIE/CIRBST/BPI Certified Building Analyst Certified Indoor Environmentalist Certified Infrared Building Science Thermographer