

ADVOCATE DESIGN/BUILD & CONSTRUCTION, LLC

880 Iron Mine Hill Road, North Smithfield, RI 02896 (401) 474-6014


RI Contactor #38650

AdvocateDBC.com

Owner: xxxx xxx xxxxxxxxxxxxxxxxxxxx

Service Start Date: 3/30/22

Service Address: xx xxxxxx Road, Smithfield, RI 02917



1)



2)

Customer found wet carpet in basement and saw water (still dripping down) to walls from above the acoustic ceiling.




3)



4)

Heavy amount of accumulated water absorbed into wall framing plate and knotty pine walls as well as carpet and pad.



5)



6)

More carpet and wall images



7)



8)

Most of the equipment as placed/operating



9)




10)
Dehumidification and ceiling drying



11)

Last basement image at emergency response to site.




12)



13)

#12) Kitchen image at emergency response
#13) Hardwood floor drying equipment 3/31/2022



14)



15)

Kitchen floor drying.



16)

Per homeowner's plumber, kitchen main feed had a leak. Lines only capped at the time of our monitoring visit 3/31/2022.

Comments and conclusion

As per caption under image 16, plumber found the leak. Insured's shut off the water main upon finding the standing water, Advocate responded that evening.

Thermal images, digital photos and moisture mapping by Todd Pascoe.

Todd Pascoe, CIE/CIRBST/FL CRMA #3961
Advocate Design/Build & Construction, LLC
(401) 474-6014