

NOREASTER DISASTER RESTORATION, LLC


1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDR CPR.COM

Property Owner: XXX XXX XXXXXX, XX Sunnyside Dr., Cumberland, RI 02864 Taken: 2/12/2015


1)




2)



3)



4)




NOREASTER DISASTER RESTORATION, LLC

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCP.R.COM


Property Owner: XXXX XXXX XXXXXX, XX Sunnyside Dr., Cumberland, RI 02864 Taken: 2/12/2015




5)



6)



7)



8)



NOREASTER DISASTER RESTORATION, LLC

CONCLUSION & COMMENTS

Loss called in to Noreaster at February 12, 2015 at 2:30 pm. We provided same day moisture mapping for water damage due to ice dams, but were conservative and DID NOT bring in any drying equipment because snow had not been completely removed from the roof, though in progress, at the home of Mr and Mrs xxxxxxxxxxxx. MOST LOSSES IN PROGRESS RIGHT NOW WHERE WE HAVE OPENED WALLS ACTUALLY HAVE ICE IN LARGE QUANTITIES IN THE WALL CAVITIES.****

INTERIM REPORT – THE LOSS HAS INCREASED IN SCOPE – THE CUSTOMER HAS NOW ADVISED THAT THE KITCHEN WINDOW IS LEAKING INTENSELY, AND MR xxxxxxxxx HAS SEEN A STREAK ON HIS GARAGE WALL COMMON WITH THE FOYER. The customer has been constantly drying the kitchen leaks with towels.

NOREASTER DISASTER RESTORATION WILL GO BACK TO THE PROPERTY TO DO ADDITIONAL SCANNING NEXT WEEK, THE FIRST WEEK OF MARCH 2015 WITH A WARMER FORECAST PREDICTED, THAT WE HOPE WILL HAVE THE ICE DAM EFFECT FINALLY CONTROLLED SO WE CAN DEVELOP A PLAN TO DRY THIS STRUCTURE. FIVE KNOWN INTERIOR ROOMS HAVE DAMAGE, PLUS THE GARAGE, ONLY FOUR SHOWN IN THIS REPORT.

**Todd Pascoe, CIE/CIRBST/BPI Certified Building Analyst
Certified Indoor Environmentalist
Certified Infrared Building Science Thermographer**