


NOREASTER DISASTER RESTORATION, LLC

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM

Property Owner: XXX XXXX XXXXX, XX Clarence St, Bellingham, MA

Taken 1/6/2014




MASTER BEDROOM AND THE AFFECTED ATTIC AREA IMMEDIATELY ABOVE IT.

NOREASTER DISASTER RESTORATION, LLC

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCPR.COM

Property Owner: XXX XXX XXX, xx Clarence St, Bellingham, MA Taken 1/6/2014



Music room adjacent to master bedroom.



NOREASTER DISASTER RESTORATION, LLC

CONCLUSION & COMMENTS

Images obtained 1/6/2014 and 1/7/2014. Comments made here are at site visit during equipment setup and during insulation removal, and during monitoring. Pipe freeze in attic of ranch home with slab floor system. We were able to save the laminate floor system. The master bedroom needs a simple drywall patch plus paint, and the adjacent (music) room with common wall needs ceiling paint. About 80 s/f of insulation is required in the attic.

No mitigation done to contents, none needed.

Todd Pascoe, CIE/CIRBST/BPI Certified Building Analyst
Certified Indoor Environmentalist
Certified Infrared Building Science Thermographer