




NOREASTER DISASTER RESTORATION, LLC

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDR CPR.COM

Property Owner: xxxx xxxxxxxx, xxx Farm Street, Blackstone, MA 01504

Taken: 2/1/2015 and 2/3/2015




These images are in the second floor bedroom/office area where leak through the ceiling and walls first was noticed by the homeowners.

NOREASTER DISASTER RESTORATION, LLC

1912 Pound Hill Road, North Smithfield, RI 02896 Phone (401) 229-2600 NDRCP.R.COM

Property Owner: xxxx xxxxxxxx, xxx Farm Street, Blackstone, MA 01504


Taken: 2/1/2015 and 2/3/2015



5)

6)

These images were obtained on February 3, 2015 – despite the removal of snow & ice prior to our original arrival date Sunday 2/1/15. The damage is increasing with additional melting.



7)

8)

The homeowner is now observing more water entering the structure, affecting the kitchen ceiling shown in images 7 and 8.



NOREASTER DISASTER RESTORATION, LLC

CONCLUSION & COMMENTS

Loss called in to Noreaster at February 1, 2015. Some contents needed to be removed from areas in the upstairs room shown in images 1 -6 to allow equipment setup on the second floor. We were contacted by Ms. xxxxxxxx that she was getting a lot of additional water on Tuesday 2/3 and it now appeared there was water coming in to the kitchen. **THIS IS AN INTERIM REPORT – THE INSURED’S INSURANCE ADJUSTER AND ROOFER ARE ALL MEETING AT THE PROPERTY THE MORNING OF 2/4/2015.**

**Todd Pascoe, CIE/CIRBST/BPI Certified Building Analyst
Certified Indoor Environmentalist
Certified Infrared Building Science Thermographer**